


optris CompactPlus Connect

Software for Infrared Thermometer



Operator's Manual



Table of contents

Table of contents	2	2.5. Sensor Setup CTratio – Display	51
Welcome!	4	2.5.1. Visual Alarms	51
Legal disclaimer	5	2.5.2. Temperature unit	52
1. Basics	6	2.6. Sensor Setup CTratio – Advanced Settings.....	53
1.1. Software installation.....	6	2.6.1. RS485 Multidrop Address	54
1.2. Connection Sensor - Computer.....	8	2.6.2. Optical Set.....	54
1.3. RS485/ RS422.....	9	2.6.3. Calibration	55
1.4. Easy Start-Up	10	3. CT	58
1.5. Basic Settings.....	11	3.1. Sensor Setup CT – Signal Processing.....	58
1.5.1. Language.....	11	3.1.1. Emissivity and Transmissivity	59
1.5.2. Options	12	3.1.2. Ambient Temperature Compensation	60
1.5.3. Diagram settings	13	3.1.3. Post Processing	61
1.6. Digital Display	14	3.2. Sensor Setup CT – Output	66
1.7. Views.....	16	3.2.1. Output 1 and 2.....	67
1.8. External Displays	18	3.2.2. Failsafe.....	69
1.9. Start measurement	20	3.2.3. Digital Output AL2	70
1.10. Scaling of the Temperature Axis	22	3.2.4. Relays	71
1.11. Stop Measurement and Save Data	23	3.3. I/O Pins	72
1.12. Measurement Configuration.....	24	3.4. Display	75
1.13. Opening of Files	25	3.4.1. Visual Alarms	75
2. CTratio	27	3.4.2. Temperature unit	76
2.1. Sensor Setup CTratio	27	3.5. Sensor Setup CT – Advanced Settings	77
2.2. Sensor Setup CTratio – Signal Processing	28	3.5.1. Sensor Setup CT – Calibration	78
2.2.1. Ratio Mode - Standard Ratio	29	3.5.2. Manual Calibration.....	79
2.2.2. Ratio Mode - Smart Ratio.....	30	3.5.3. 1 Point Calibration	80
2.2.3. Post Processing.....	41	3.5.4. 2 Point Calibration	81
2.3. Sensor Setup CTratio – Output	44	3.5.5. USB Communication	82
2.3.1. Output 1 and 2	44	3.5.6. RS485-Multidrop address	82
2.3.2. Failsafe.....	47	3.5.7. Locking the programming keys	83
2.4. Sensor Setup CTratio – I/O pins	48	4. Special Feature	84
		4.1. Saving the Sensor Configuration	84
		4.2. Smart Averaging	85
		4.3. Binary Chat Program.....	86

4.3.1. Additional Features	88	5.6. Menu: Preferences	95
5. Menu Overview	89	5.7. Menu: Help	95
5.1. Menu: File	89	5.8. Context Menu (right mouse button)	96
5.2. Menu: Measurement	90	5.9. Context Menu [Sub menu: View]	97
5.3. Menu: Device	91	5.10. Context-Menu [Sub menu: External Display]	98
5.4. Menu: Diagram	92		
5.5. Menu: View	93		


Welcome!

Thank you for choosing an infrared thermometer and corresponding CompactPlus Connect software!

The sensor calculates the surface temperature based on the emitted infrared energy of objects [► **Basics of Infrared Thermometry**].

Main features of CompactPlus Connect software:

- Temperature data analysis and documentation
- Automatic process control
- Customer specific software adjustments
- Complete parameterization of the device
- Temperature display and recording



Legal disclaimer

All products are warranted against defective materials and workmanship for a period of two (2) years from the delivery date of the original purchase, provided such products have been under normal storage, use and service, and in accordance with the instruction. This warranty expires in case of inappropriate use of all delivered components.

All products not manufactured by us included in systems delivered by us to the original purchaser carry the warranty, if any, of the particular supplier only and we have no responsibility whatsoever for such products. The manufacturer is not liable for any use of the software CompactPlus Connect including data recording. The manufacturer does not carry liability for error-free operation of the software in any hardware and operating system.

The warranty is not expressed for possible quality changes, errors when presenting the software, occurring defects during operation or insufficiencies in certain applications. The user is liable for any defects or data processing insufficiencies when in using the software.

The manufacturer has no other liability inside the scope of supply other than mentioned above. The manufacturer shall not be liable for any business loss or claim for compensation, loss of the computer software, possible loss of data, additional costs for replacement software, claims of third parties or other occurring costs or failures and deficits.

The software is protected by copyright and is not allowed to be changed or sold to third parties.

Optris GmbH
Ferdinand-Buisson-Str. 14
13127 Berlin
Germany

Phone: +49-30-500 197-0
Fax: +49-30-500 197-10

E-mail: info@optris.global
Internet: www.optris.global



Note

Read the manual carefully before you start the device. The manufacturer reserves the right to change the herein described specifications in case of technical advance of the product.

1. Basics

1.1. Software installation

Download the software from the Optris website. Please start **Setup.exe** and follow the instructions of the wizard until the installation is finished.

Minimum system requirements:

- Windows 7, 8, 10
- USB interface
- Hard disc with at least 30 MByte free space
- At least 128 MByte RAM

The installation wizard will place a launch icon on the desktop and in the start menu:
[Start]\Programs\CompactPlus Connect.



When using the Ethernet interface, the driver must be installed separately. This can be found in the download package in the Driver folder (Name: Ethernet).



Note

The software can be downloaded via the Optris website under the following link:
<https://www.optris.global/downloads-software>

IRmobile App

The pyrometers have a direct connection to an Android smartphone or tablet. All you have to do is download the IRmobile app for free in the Google Play Store. This can also be done via the QR code.




Note

The IRmobile app works on most Android devices running 5.0 or higher with a micro USB or USB-C port supporting USB-OTG (On The Go).

1.2. Connection Sensor - Computer


If you connect your sensor to your PC and start the software, the following message will appear (if option **Auto Start** is activated). ► **Menu Preferences/ [Options](#)**

Then please press the **Scan** button. All sensors found will be shown in a selection screen:



Example 1: A sensor was found. Press **Select** to close the window.

Refresh starts a new search.



Example 2: Two sensors were found. Please activate with the cursor the desired unit and after that press the **Select** button to close the window.

Refresh starts a new search.

After the selection of a sensor you will get to the previous screen again. Here you will find now information about the used virtual COM port (VCP), the serial number and the baud rate.

To finish please press **OK**. The window will be closed.

If **Auto start device** is activated ► **Menu Preferences/ Options** the measurement starts and the temperature values will be shown in the diagram.

After the sensor selection the status line (below the time axis) shows the following information:

COM75: Opened | CTRatio : Measuring

COMxx: Opened active COM port

CTRatio: Measuring successful communication with the connected sensor

1.3. RS485/ RS422



If a RS485 interface is used please activate the RS422 mode. Therefore you have to call this function with the programming keys on the sensor at first (menu item: multidrop address). You will need also the RS485 module and the RS485-USB adapter **[ACCTRS485USBK]**.

1.4. Easy Start-Up

If you restart the software and the last used sensor is connected to the computer and the **Auto Start** option is activated ► **Basic Settings/ Options** the connection will be made automatically (without sensor selection window).

If this option is deactivated, you must select the corresponding device in **[Menu: Device\ Scan Devices]** and press the **Select** button.



The button **Disconnect** in **[Menu: Device]** breaks the connection to the sensor and closes the COM port.



1.5. Basic Settings


1.5.1. Language

You can choose the desired **language** in the menu **[Menu: Preferences\ Language]**.



1.5.2. Options

The menu item **[Menu: Preferences\ Options]** allows the following settings:



Auto Start

If activated, after each program start the measurement will be started automatically (if connected sensors have been found before).

Auto Apply

If activated the changing of the settings will be directly effected

Fahrenheit


If activated, the temperature is displayed in Fahrenheit.

The further options are described under [▶ **Stop Measurement and Save Data.**](#)

1.5.3. Diagram settings

The menu item Settings **[Menu: Diagram\ Settings]** enables the selection of the following diagram options:

- Digital Display** Selection which signals should be displayed as digital display
- Diagram** Selection which signals should be displayed as graph
- Pen Width** Pen width of the temperature graphs **[1...5]**
- Color** Color of the temperature graph and digital displays
- Y-axis** Time frame on the y-axis, which should be displayed at the beginning of a measurement



1.6. Digital Display

If the sensor is connected to your computer and you start the software, the process temperature T_{Proc} will be shown as digital display (top right). You can add additional displays [**Menu: View\ Digital**]. Dependent on the sensor type the available signals may vary.

T_{Proc} includes the current post processing functions (average, peak hold, etc.).

The once selected displays will also appear after a restart of the software. The **size** can be changed if you put the cursor on the line beneath the display and pull it down. The buttons of the tool bar will also be moved (depending on the display size).

The colors of the different displays are equal to the colors selected under [**Menu: Diagram\ Settings**] for the corresponding temperature graphs.
► **Basic Settings**



Overview of Digital Display

Notation		Description
T_{Proc}	Process temperature	With signal processing, including averaging
T_{Ratio}	Ratio temperature	Without signal processing, including averaging
T_1	1-channel temperature	Without signal processing, including averaging
T_2	2-channel temperature	Without signal processing, including averaging
$T_{ActRatio}$	Actual temperature of ratio	Without signal processing, without averaging
T_{TAct1}	Actual temperature of channel 1	Without signal processing, without averaging
T_{TAct2}	Actual temperature of channel 2	Without signal processing, without averaging
Attenuation	Signal attenuation	Signal attenuation
T_{Det} / T_{Int}	Head temperature	Temperature value of detector
T_{Box}	Box temperature	Temperature of electronic box
T_{Avg}	Average temperatur	Without signal processing, including averaging




Note

The available temperatures depend on the connected device type

1.7. Views


The CompactPlus Connect allows the creation of free definable screens and views:



Note


The digital displays can be arranged optional on top or right side [Menu: View\ Temp. displays top or Temp. displays right].

You can show the digital displays also separate by hiding of selected information (e.g. title bar, menu bar, etc.) in any size ► **Digital Displays** and, if desired, also always on top of your PC screen [**Menu: View\ Always on top**].



1.8. External Displays


By double click on one of the digital displays **[Menu: View\ External Display]** you can start an external display for the respective signal. This display will appear initially in the same color than the respective display in the software. By drag and drop these external displays can be placed at any desired location on the PC screen (the position of the according software display will not change). For an easy positioning a mark will appear on the left of the display if crossed with the cursor:



Note


To distinguish between several displays the name of the software/ instance (for multiple software calls) as well as the signal name will be shown shortly.

There are different options available for the design of the external displays which can be called with the right mouse button:



Border

Presenting the display with a border – in this mode the size of the display can be changed.




Transparent

Transparent presenting – useful for a positioning of the display in front of pictures or wallpapers.



Change color

For changing the display color.



Use contrast color

Dependent on the used background the presenting of the display figures with contrast color (black edging) can be useful.




Remove Display

Closes the associated external display.

1.9. Start measurement

To start a measurement, please press the **Start** button in the tool bar [**Menu: Measurement\ Start**].




Control elements of the time axis:

- 1 Scroll bar
- 2 Zoom in (increase)
- 3 Zoom out (decrease)
- 4 Whole range
- 5 H: Hold/ C: Continue



Any activation of a control element of the time axis or of the **Pause** button will stop the further actualization of the measurement graph. The measurement itself continues in the background. To return to the current measurement graph please press the **Pause** button again [**Menu: Measurement\ Pause**] or **C**.



During the stopped status any parts of the diagram can be selected with the **Time scroll bar**. With the zoom in-button **+** these parts can be stretched (enlarged) and with the zoom out-button **-** clinched (minimized).

1.10. Scaling of the Temperature Axis

With **global scaling** the temperature range of the diagram will automatically be adapted to the respective peak values. The range will remain as set during the whole measurement.


With **local scaling** the temperature range of the diagram will be adapted dynamically to the respective peak values. After the respective peak has left the diagram in the further process of the measurement, the range will be readapted. This option enables an optimum display of the temperature graph.

A **manual scaling** can be done at any time using the control elements of the temperature axis.

**Activation of the desired option:
Control elements (temperature axis)**

Control elements of the temperature axis:


- 1 Global auto scaling
- 2 Local auto scaling
- 3 Scroll bar
- 4 Zoom in (increase)
- 5 Zoom out (decrease)
- 6 Whole range



1.11. Stop Measurement and Save Data


To stop the current measurement please press the **Stop** button
[Menu: Measurement\ Stop].

The **Save** button [Menu: File\ Save as] opens an explorer window
to select destination and file name [file type: *.dat].




1.12. Measurement Configuration

With the menu item [**Menu: Measurement\ Settings**] you can define the following parameter for the measurement:



Max. data count	Limitation of the maximum number of data values – when achieved the measurement will be stopped.
Stop/ Overwrite	If the maximum number of data values is achieved, at Stop the current measurement will be terminated automatically/ at Overwrite the measurement will continue and the first values will be overwritten (principle of ring memory)
Memory	Memory, calculated from the max. data count value
Recording interval	Time between single data [1ms...10s]



Recording time Maximum time of measurement, calculated from **Max data count** and **Recording interval**



Note


A change of the parameter **Max data count** will have influence on the **Memory** and **Recording time**.

A change of the parameter **Recording interval** will have influence on the **Recording time** only.

Communication mode At **Auto** setting (recommended) the connected sensor works in **Realtime mode** (=Burst mode: Sensor is sending data continuously) if the recording interval is <200 ms. If the recording interval is >200 ms the sensor works in the **Standard mode** (= Polling mode: Temperature values will be polled by the software).

1.13. Opening of Files

To open a saved file please press the button **Open** [Menu: **File\ Open**]. You can select the desired file in an explorer window which will be opened [file type: *.dat].



Note

The temperature files can also be opened and edited with any text editor or with Microsoft Excel.

If you open a file with a spreadsheet program you will find beside the relative time (starting with 000:00:00 – column A) also the absolute time for each measurement value (column N).
 On video devices and if the function “Automatic Snapshots” is activated you will find further information to the recorded snapshots in the columns O and P:


	A	B	C	D	E	F	G	H	I	J	K
1	[Connect DataFile][1.1]										
2	Date:	01.11.2019									
3	Time:	28:12,2									
4	Unit:	°C									
5	Resolution:	0,001									
6	Values:	10									
7	Time	TProc	TRatio	T1	T2	TActRatio	TAct1	TAct2	Attenuati	THead	TBox
8	00:00,0	525	525	506,2	499	525	506,3	499,5	100	60,3	38,9
9	00:00,1	525	525	506,2	499	525	506,2	499	100	60,3	38,9
10	00:00,2	525	525	506,2	499	525	506,3	499,3	100	60,3	38,9
11	00:00,2	525	525	506,2	499	525	506,4	499,5	100	60,3	38,9
12	00:00,3	525	525	506,2	499	525	506,6	499,6	100	60,3	38,9
13	00:00,4	525	525	506,3	499,1	525	506,5	499,4	100	60,3	38,9
14	00:00,5	525	525	506,5	499,3	525	506,5	499,3	100	60,3	38,9
15	00:00,6	525	525	506,6	499,4	525	506,6	498,9	100	60,3	38,9
16	00:00,7	525	525	506,5	499,3	525	506,4	498,9	100	60,3	38,9

2. CTratio

2.1. Sensor Setup CTratio

The button **Setup** [Menu: **Device\ Device Setup**] opens a window for the setting of all sensor parameters. The dialog window is separated into 4 categories:

- Signal processing Setting of Emissivity/ Slope and Post processing
- Output Setting of Output 1 and Output 2
- I/O Pins Setting the In- and Outputs
- Display Display main value and Backlight/ Alarm setting
- Advanced settings RS485 Multidrop address, Optical Set, Calibration



CTratio

2.2. Sensor Setup CTratio – Signal Processing

In this category you can adjust the parameters **Emissivity**, **Slope**, **Attenuation** and select the functions and define the parameters for **Post processing**. Furthermore, the desired ratio mode can be selected here. The Standard Ratio mode is activated as default setting.

The screenshot shows the 'Configuration' window for the sensor, with the 'Signal Processing' tab selected. The window displays the following settings:

- Serial Number:** 20092003
- Firmware Rev.:** 10014
- Ratio Mode:** Standard Ratio, Smart Ratio
- Standard:**
 - Slope: 1,000
 - Emissivity/Transmission 1: 1,000
 - Emissivity/Transmission 2: 1,000
 - Calculate Slope/Emissivity: [Button]
 - Process Temperature: 500,0
- TRatio [°C]:** 275,0
- T1 [°C]:** 250,0
- T2 [°C]:** 250,0
- Attenuation [%]:** 100,0
- Post Processing:**
 - Source: TRatio
 - Averaging:
 - Averaging Time [s]: 0,020
 - Averaging Mode: Normal
 - Smart Averaging Hysteresis [K]: 5,0
 - Hold:
 - Mode: Off
 - Time [s]: Infinite, 10,000
 - Threshold [°C]: 1000,0
 - Hysteresis [K]: 10,0
- Max Attenuation Reached Behavior:**
 - Max Atten. [%]: 95,00
 - Max Atten. Mode: Last valid value
- Buttons:** Load Config, Save Config, Factory default, OK

2.2.1. Ratio Mode - Standard Ratio

Emissivity/ Slope/ Attenuation

The **Slope** is the quotient of the emissivity's of both of the overlapping wavelengths and therewith the deciding parameter for measurements in 2-color-mode.

The **Emissivity** (ϵ – Epsilon) is a material constant factor to describe the ability of a body to emit infrared energy. The emissivity only affects measurements in the 1-color-mode.

The function **Calculate Slope/Emissivity** allows the determination of an unknown emissivity and slope at a known process temperature.

Ratio Mode

Standard Ratio Smart Ratio

Standard

Slope 1,000

Emissivity/Transmission 1 1,000

Emissivity/Transmission 2 1,000

Calculate Slope/Emissivity

Process Temperature: 500,0

TRatio [°C] 275,0

T1 [°C] 250,0

T2 [°C] 250,0

Attenuation [%] 100,0

Attenuation

Max Attenuation [%] 95,00 Min Attenuation [%] 0,00

Max Attenuation Mode Last valid value Min Attenuation Mode Last valid value

Attenuation: The temperature display is fixed if the attenuation exceeds the limit specified here. You can decide whether the **last valid value** should be kept or a **fixed value** entered. This can be selected for **maximum** and **minimum attenuation**.

2.2.2. Ratio Mode - Smart Ratio

While the standard mode requires a constant emissivity ratio/slope, the **Smart Ratio** measurement allows a data set of different slopes to be recorded and applied for temperature calculation. This is required, for example, if the degree of contamination of the protective window changes during the process and the ratio temperature is no longer correct. This cannot be described with a constant slope.

The screenshot displays the 'Ratio Mode' control interface. At the top, there are two radio buttons: 'Standard Ratio' (unselected) and 'Smart Ratio' (selected). Below this, the 'Smart' section contains two buttons: 'Teach-In' and 'Off'. To the right, there are four input fields for numerical values: 'TRatio [°C]' with a value of 275,0; 'T1 [°C]' with a value of 250,0; 'T2 [°C]' with a value of 250,0; and 'Attenuation [%]' with a value of 100,0.

A requirement for the measurement is that the object temperature must be known.

Note: Before the first use a data record must be recorded


In the **Teach-in** function, the data records are recorded.

The Smart Ratio mode can be activated or deactivated with the **On/Off** buttons.

Teach-In

The process temperature must be known for the teach-in function. This temperature can be set using two variants:


- **Variant 1: Via a fixed value**
Here the known process temperature is entered manually.
- **Variant 2: Via Uncommitted value**
The input is done via an analog signal, for example an external sensor.



Procedure

Hold the dirty window in front of the sensor.


The **Measure Now button (F12)** can now be used to record measuring points. The current transmission and slope are entered into the table. Alternatively, the **F12** button can be pressed.



Note



When recording different measuring points, the current process temperature must always be taken into account. At least two measuring points with different degrees of contamination. Recommendation: The more measuring points the better




Smart Ratio example with 11 measuring points

The middle figure shows the transmission of diode 1 relative to the transmission of diode 2

The blue points are the recorded measuring points.

Green curve: Regression curve (polynomial) for calculating the values between the measuring points.



Note



The Smart Ratio method can only work if there is a monotonically increasing function progression. If this is not the case, the Smart Ratio method cannot be used. If this is not the case, repeat the measurement and check the measurement for measurement errors.


The right figure shows the transmission ratio (slope) relative to the transmission of diode 2.

The blue points are the recorded measuring points.


The violet horizontal line is the average slope calculated from the measured values.


The red curve is an estimate of the quotient temperature error (in Kelvin) when using the average slope without the Smart Ratio method.

Green curve: Regression curve (polynomial) for calculating the values between the measurement points.





To write the created curves to the device, the **Apply Smart Ratio with new data** option must be selected in the menu under **Apply Correction Method**. The created regression curve is now written to the device. A message window appears indicating that the table is being saved to the device. The Smart Ratio mode is now automatically activated.






Smart ratio mode is now activated. Further data points can no longer be recorded in this mode. To add more data points, press the **Continue Data Acquisition** button (Smart Ratio mode is deactivated again).

After successful setting you can close the window with the **OK** button.



Activation of the Smart Ratio function is indicated by a green illuminated **On** button. In addition, there is an icon called **SRM**, which is framed in green when activated.

To deactivate the Smart Ratio function, you can either click on the icon or on the green on button.




Further Settings

Further settings can be made in the menu under **File**.

Save measurement points to CSV file: The created data is stored on a hard disk.

Save regression data to device: The created data is stored on the device without activating or applying the Smart Ratio method.



Save regression data to .dat file: Here the data is stored on a hard disk for external data analysis.

Load measurement points from CSV file: If data sets already exist, the values can be read in and loaded into the table.

Load regression data from device: To view the currently used regression curve.

Load regression data from file: The regression data is loaded from an existing file.

Load regression data from file and save to device: Here the regression data is loaded from an existing file and saved directly to the device.

The following settings can be made in the menu under **Data Acquisition**.


Measure Now: A single measuring point is created and written to the table.

Start periodic measurement: A predefined interval can be entered, in which the measuring points will be recorded automatically.

Stop periodic measurement: The recording of new measuring points is stopped.

Averaging count: Signal averaging during transmission measurement (response time is extended).

Delete all measurement points: All measuring points in the table are deleted (not from the device).




Note

To delete individual measuring points, you must mark them in the table and remove them with the delete key.

The following settings can be made in the menu under **Data Analysis**.

Polynom of order: The polynomial order is specified here. The factory setting is Auto and is determined automatically. Alternatively, it can be changed manually if required.




Regression accuracy: Characteristic value to evaluate the description of the measured values by the polynomial. Larger values are better. A value of 1 means perfect agreement. The regression accuracy is calculated automatically.

Average slope: The mean value of all slopes is calculated (violet straight line in the right diagram). The default setting is Auto. Alternatively it can be set manually. Allows to manually move the average slope (display optimization).

The following settings can be made in the menu under **Apply**.

Apply Smart Ratio with new data: The created regression curve is written to the device and the Smart Ratio mode is activated. A message window appears indicating that the table is being saved to the device.



Apply Smart Ratio with old data: Regression curve already stored in the device is retained and Smart Ratio mode is activated.

Apply average slope: Set average slope and activate standard ratio mode.

Apply old slope: Restore the slope value before opening the Smart Ratio configuration.

2.2.3. Post Processing

In the category **Post Processing** you can select the **Source** and make following settings:

- **Averaging** (Averaging time, average mode, smart threshold)
- **Hold** mode (Mode: Off, Peak Hold, Valley Hold, Advanced Peak Hold, Advanced Valley Hold)

You will find the description of the single functions on the next page.

Smart Averaging

If activated, a dynamic average adaptation at high signal edges is active. In addition you can enter the minimum temperature difference (**Smart Averaging Hysteresis**) to trigger this function.

Post Processing

Source TRatio

Averaging

Averaging Time [s] 0,020

Averaging Mode Normal

Smart Averaging Hysteresis [K] 5,0

Hold

Mode Off

Time [s] Infinite

Threshold [°C]

Hysteresis [K] 10,0

Averaging

In this mode an arithmetic algorithm will be performed to smoothen the signal. The **Averaging Time** is the time constant. This function can be combined with all other post processing functions. The minimum adjustable average time is 0,001 s.

Peak hold

In this mode the sensor is waiting for descending signals. If the signal descends the algorithm maintains the previous signal peak for the specified **Hold time**.

The minimum adjustable hold time is 0,001 s.

After the hold time the signal will drop down to the second highest value or will descend by 1/8 of the difference between the previous peak and the minimum value during the hold time. This value will be held again for the specified time. After this the signal will drop down with slow time constant and will follow the current process temperature.

Therefore, if periodic events will be measured (bottles on a conveyor e.g.) this peak hold function avoids a drop down of the signal to the conveyor temperature in-between 2 events.

Valley hold

In this mode the sensor waits for ascending signals. If the signal ascends the algorithm maintains the previous signal valley for the specified **Hold time**. The definition of the algorithm is according to the peak hold algorithm (inverted).

Advanced Peak hold

In this mode the sensor waits for local peak values. Peak values which are lower than their predecessors will only be taken over if the temperature has fallen below the **Threshold** value beforehand. If **Hysteresis** is activated a peak in addition must decrease by the value of the hysteresis before the algorithm takes it as a new peak value.

Advanced Valley hold

This mode is the inverted function of Advanced Peak hold. The sensor waits for local minima. Minimum values which are higher than their predecessors will only be taken over if the temperature has exceeded the **Threshold** value beforehand. If **Hysteresis** is activated a minima in addition must increase by the value of the hysteresis before the algorithm takes it as a new minimum value.

Smart Averaging

If activated, a dynamic average adaptation at high signal edges is active.

Off


If **Off** is activated, no post processing will happen.

2.3. Sensor Setup CTratio – Output

2.3.1. Output 1 and 2


The device has two outputs (**OUT 1**, **OUT 2**) which can be configured as desired. The following options are available under **Mode**:

- Off
- Analog
- Alarm



When Analog is activated, the following signal sources can be selected in the Source field:

- **TProc** Process temperature
- **TRatio** Ratio temperature
- **T1** 1 channel temperature
- **T2** 2 channel temperature
- **Attenuation** Signal attenuation in %
- **TDet** Temperature of detector
- **TBox** Box temperature



The desired temperature measuring range of the sensor can now be set. The range limits can be changed by entering them in the corresponding fields. The source can be selected between **T_{Proc}**, **T_{Ratio}**, **T₁**, **T₂**, **Attenuation**, **T_{Det}** or **T_{Box}**.

- **TMin**: lower temperature range limit
- **TMax**: upper temperature range limit
- **Min [mA]**: lower limit mA output
- **Max [mA]**: upper limit mA output

The screenshot shows the 'Output' configuration page for 'Output 1'. The 'Mode' is set to 'Analog'. Under the 'Analog' section, the 'Source' is 'TProc'. The 'FailSafe Min Range [°C]' is 700,0 and the 'FailSafe Max Range [°C]' is 1400,0. The 'TMin [°C]' is 700,0 and the 'TMax [°C]' is 1400,0. The 'FailSafe min [mA]' is 0,0 and the 'FailSafe max [mA]' is 20,1. The 'min [mA]' is 4,0 and the 'max [mA]' is 20,0. The 'FailSafe is Active min' checkbox is unchecked, and the 'FailSafe is Active max' checkbox is checked.

Parameter	Value
Mode	Analog
Source	TProc
FailSafe Min Range [°C]	700,0
FailSafe Max Range [°C]	1400,0
TMin [°C]	700,0
TMax [°C]	1400,0
FailSafe min [mA]	0,0
FailSafe max [mA]	20,1
min [mA]	4,0
max [mA]	20,0
FailSafe is Active min	<input type="checkbox"/>
FailSafe is Active max	<input checked="" type="checkbox"/>

Alternatively, outputs 1 and 2 can be used as alarm outputs. To do this, select the Alarm setting. As source you can choose between T_{Proc} , T_{Ratio} , T_1 , T_2 , **Attenuation**, T_{Det} or T_{Box} .

Under **Threshold** the threshold value for triggering the alarm is defined.

Hysteresis: Setting the minimum hysteresis

Alarm Off [mA/mV]: Value if no alarm

Alarm On [mA/mV]: Value on alarm

Selecting **Open/Closed** under **Mode** defines the output as High or Low alarm.

Difference Mode: When activated, no absolute value is used for the alarm threshold, but the difference between process temperature and ambient temperature ($T_{Proc}-T_{Um}$).

The screenshot shows the configuration for 'Output 2'. The 'Mode' is set to 'Alarm'. Under the 'Alarm' section, the 'Source' is 'TProc', 'Threshold [°C]' is 900,0, 'Hysteresis [°C]' is 10,0, 'Alarm Off [mA]' is 4,0, and 'Alarm On [mA]' is 20,0. The 'Mode' is set to 'Open' and 'Difference Mode' is set to 'Inactive'.

Output 2	
Mode:	Alarm
Alarm	
Source	TProc
Threshold [°C]	900,0
Hysteresis [°C]	10,0
Alarm Off [mA]	4,0
Alarm On [mA]	20,0
Mode	Open
Difference Mode	Inactive

2.3.2. Failsafe

The pyrometer has a failsafe function that can be used in analog mode.

The range can be configured as desired. The settings for fail-safe operation allow a defined level to be output at the analog output depending on specified temperature limits.

Thus, a possible cable defect can be detected quickly.

FailSafe Min Range [°C]	700,0
FailSafe Max Range [°C]	1400,0
FailSafe min [mA]	0,0
FailSafe max [mA]	20,1
<input type="checkbox"/> FailSafe is Active min	
<input checked="" type="checkbox"/> FailSafe is Active max	

2.4. Sensor Setup CTratio – I/O pins

The CTratio has three I/O pins which can be programmed as in- or outputs using the software. The following options are available:

<u>Function</u>	<u>I/O pin acts as</u>	<u>Description</u>
Alarm	output (digital)	Open collector output/ definition as HIGH- or LOW alarm via norm. open/norm. close options in software dialog.
Valid Low	input (digital)	The output follows the process temperature as long as there is a Low level at the I/O pin. After discontinuation of the Low level the last value will be held.
Valid High	input (digital)	The output follows the process temperature as long as there is a High level at the I/O pin. After discontinuation of the High level the last value will be held.
Hold Low-High	input (digital)	The last value will be held if there is a signal with a rising edge on the I/O pin.
Hold High-Low	input (digital)	The last value will be held if there is a signal with a falling edge on the I/O pin
Hold Reset Low	input (digital)	Reset of a hold function on a Low level at the I/O pin
Hold Reset High	input (digital)	Reset of a hold function on a High level at the I/O pin
Slope external	input (analog)	External adjustment of the slope value using an analog voltage (0-10 V)
Emissivity external	input (analog)	External adjustment of the emissivity value using an analog voltage (0-10 V)
Uncommitted Value	input (analog)	Display of a freely scalable value
Laser on Low	input (digital)	Switch on laser (Low signal)
Laser on High	input (digital)	Switch on laser (High signal)

Low-/High-level: via software

If you select the function **Alarm** the following signal sources can be selected:

- **TProcess** Process temperature
- **TRatio** Ratio temperature
- **T1** 1 channel temperature
- **T2** 2 channel temperature
- **Attenuation** Signal attenuation in %
- **TDet** Detector temperature
- **TBox** Box temperature

The definition as Low or High alarm can be done by switching between **Normally: open** and **Normally: closed**.

If you select the function **Slope external** or **Emissivity external** the I/O pin is set as analog input. The scaling can be done using the parameter fields **P1/P2** and **Slope P1/P2 / Epsilon P1/P2**.

I/O Pin 1

Mode

Parameter

Source

Threshold [°C]

Hysteresis [°C]

Normally

Difference Mode

I/O

OUTPUT

I/O Pin 2

Mode

Parameter

P1 [V]

P2 [V]

Slope P1

Slope P2

I/O

INPUT

If you select the function **Hold Reset Low** or **Hold Reset High** the I/O-Pin is set as digital input. An activated hold function (MAX, MIN, advanced MAX, advanced MIN) will be reset if a low or high level is at the I/O pin.

I/O Pin 3

Mode Hold Reset Low

Parameter

Threshold [V] 0,0

Hysteresis [V] 0,0

I/O

INPUT

2.5. Sensor Setup CTratio – Display

In this tab you can make settings for the display and the backlight (=visual alarms). Furthermore, the temperature unit can be selected here.

2.5.1. Visual Alarms

Independent of the selected signal for the analog output, a signal from the following list can be selected under General/ Main display source, which is shown in the digital display of the electronics:

TProc	Process temperature
TRatio	Ratio temperature
T1	Temperature value 1-color-mode
T2	Temperature value 2-color-mode
Attenuation	Signal attenuation in %
TDet	Temperature of the detector
TBox	Temperature of the electronics

For the visual alarm areas up to eight alarm limits can be assigned to a signal. The selected signal can be selected under **Source** independent of the value shown in the display and independent of the analog output.

Signal Processing Output I/O Pins **Display** Advanced Settings

General

Main Display Source: TProc

Temperature Unit: Celsius

Visual Alarms

Source Attenuation

From	To			
400,0 [%]	405,0 [%]	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
410,0 [%]	415,0 [%]	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
420,0 [%]	425,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
430,0 [%]	435,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
440,0 [%]	445,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
450,0 [%]	455,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
460,0 [%]	465,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
470,0 [%]	475,0 [%]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

2.5.2. Temperature unit

Selection between °C and °F as temperature unit.

Temperatureinheit: °C °F °C

2.6. Sensor Setup CTratio – Advanced Settings

In the category **Advanced Settings** the following parameter can be adjusted:

- RS485 - Multidrop address
- Optical Set
- Calibration

The screenshot displays the 'Advanced Settings' tab of a software interface. The tab is highlighted with a red border. The interface is divided into three main sections: RS485, Optical Set, and Calibration.

RS485: Contains a 'Multidrop Address' dropdown menu set to '1'.

Optical Set: Contains a 'Number' dropdown menu set to '1'.

Calibration: Contains a 'Mode' dropdown menu set to 'Manual'. Below it are three sub-sections, each with 'Offset [K]' and 'Gain' dropdown menus:

- Ratio:** Offset [K] is 0,0; Gain is 1,00000.
- T1:** Offset [K] is 100,0; Gain is 1,00000.
- T2:** Offset [K] is 100,0; Gain is 1,00000.

2.6.1. RS485 Multidrop Address

In combination with a RS485 interface you can build a network of several CTratio sensors (max. 32 sensors).

For the digital communication each sensor must have its own address which you can enter in the input field Multidrop address.

[▶ RS485/ RS422](#)

RS485

Multidrop Address:

2.6.2. Optical Set

If replacement fibers are used, the correct number must be entered for exact allocation. Each fiber has a unique number.

Optical Set

Number

2.6.3. Calibration

In the Advanced Settings tab, three different modes can be selected to perform a calibration of the device:

- Manual
- 1 Point (Calibration)
- 2 Point (Calibration)

These amplification factors can be entered for the Ratio, T1 and T2 temperature.

Manual Calibration

For certain applications or under certain circumstances a temperature offset or a change of the gain for the temperature curve may be useful.

The **factory default settings** for Offset and Gain are:

- Offset: 0,0 K
- Gain: 1,000


The screenshot shows a 'Calibration' settings window. At the top, there is a 'Mode' dropdown menu set to 'Manual'. Below this, there are three sections: 'Ratio', 'T1', and 'T2'. Each section contains two input fields: 'Offset [K]' and 'Gain'. The 'Ratio' section has an Offset of 0,0 and a Gain of 1,00000. The 'T1' section has an Offset of 100,0 and a Gain of 1,00000. The 'T2' section has an Offset of 100,0 and a Gain of 1,00000. All input fields have a small up/down arrow icon on the right side.

A changed **Offset** causes a parallel shifting of the temperature curve and therewith it has a linear effect on the temperature reading (change constant independent on process temperature). A change of the **Gain** will have a non-linear effect on the temperature reading (change depends on process temperature).

1 Point Calibration

In this mode, a 1-point calibration can be made for the device. To do this, select under Mode **1 Point** (Calibration) and enter the **actual temperature** and the **set temperature**. An offset calculation takes place and is displayed.

Calibration	
Mode	1 Point
Ratio	
Offset [K]	0,0
Gain	0,99415
T1	
Offset [K]	0,0
Gain	0,00001
T2	
Offset [K]	0,0
Gain	0,00001



P1	
Set Temperature [°C]	855,0
Actual Ratio Temperature [°C]	855,0
Actual T1 Temperature [°C]	0,0
Actual T2 Temperature [°C]	0,0

2 Point Calibration

In this mode, a 2 point calibration can be made. To do this, select under Mode **2 Point** (Calibration) and enter the **actual temperature** and the **set temperature** for two different points. An offset and gain is then calculated.

Calibration

Mode

Ratio

Offset [K]

Gain

T1

Offset [K]

Gain

T2

Offset [K]

Gain

Set Temperature [°C]	Actual Ratio Temperature [°C]	Actual T1 Temperature [°C]	Actual T2 Temperature [°C]
815,0	850,0	0,0	0,0
1415,0	1390,0	0,0	0,0

P1

Set Temperature [°C]

Actual Ratio Temperature [°C]

Actual T1 Temperature [°C]

Actual T2 Temperature [°C]

P2

Set Temperature [°C]

Actual Ratio Temperature [°C]

Actual T1 Temperature [°C]


Actual T2 Temperature [°C]

3. CT

3.1. Sensor Setup CT – Signal Processing

The button **Setup** [Menu: Device\ Device Setup] opens a window for the setting of all sensor parameters. The dialog window is separated into 5 categories:

- Signal processing Setting of Emissivity/ Transmission and Post processing
- Output Setting of Output 1 and Output 2
- I/O Pins Setting the In- and Outputs
- Display Display main value and Backlight/ Alarm setting
- Advanced settings Calibration, USB connection, RS485 Multidrop address



CT

3.1.1. Emissivity and Transmissivity

Under **Emissivity/Transmission** in the **Signal Processing** tab, you can set the two parameters:

Emissivity: The **Emissivity** (ϵ – Epsilon) is a material constant factor to describe the ability of a body to emit infrared energy. The emissivity only affects measurements in the 1-color-mode.

Transmission: In the input field **Transmission** you have to enter the transmission of optional optical components like an additional lens (e.g. CF optics **ACCTCF**) or a protective window (e.g. **ACCTPW**).



The screenshot shows the 'Signal Processing' tab selected in a software interface. The 'Emissivity / Transmission' section contains two input fields: 'Emissivity' and 'Transmission', both set to '1,000'. The 'TProc [°C]' field is set to '21,0'. The 'Signal Processing' tab label is highlighted with a red box.

Tab	Output	I/O Pins	Display	Advanced Settings
Signal Processing				
Emissivity / Transmission				
Emissivity	1,000		TProc [°C]	21,0
Transmission	1,000			

3.1.2. Ambient Temperature Compensation

In dependence on the emissivity value of the object a certain amount of ambient radiation will be reflected from the object surface. To compensate this impact, the software provides the feature **Ambient control**:

- **Internal (Head):** The ambient temperature will be taken from the head-internal Pt1000 probe (factory default setting).
- **Fixed value:** A fixed value can be entered in the edit box **Fixed value** (if the ambient radiation is constant).

External Ambient Compensation

Mode

Fixed value [°C]

To Configure External Ambient Compensation, please use the I/O Pins



Note

Especially if there is a big difference between the ambient temperature at the process and head temperature the use of Ambient control with **Fixed value** or via the I/O pins (mode: **External Ambient Compensation**) is recommended.

3.1.3. Post Processing

Under **Post Processing** you can set the **averaging** and **hold mode**.

Averaging: In this mode an arithmetic algorithm will be performed to smoothen the signal. The **Averaging Time** is the time constant. This function can be combined with all other post processing functions.

The minimum adjustable average time is for the CT 4M model 1ms (0,001s). On this model values below 0,1 s can be increased/ decreased only by values of the power series of 2 (0,002, 0,004, 0,008, 0,016, 0,032, ...).

Under the **Averaging Mode** you can choose between **Normal** and **Adaptive**. With Adaptive, a dynamic adjustment of the averaging process is performed for steep signal edges (**Smart Averaging**).

Post Processing

Averaging

Averaging Time [s] 0,020

Averaging Mode Normal

Smart Averaging Hysteresis [K] 5,0

Hold

Mode Off

Time [s] Infinite

Threshold [°C]

Hysteresis [K] 10,0

The following post-processing functions are available:

Off

If **Off** is activated, no post processing will happen ($T_{Proc} = T_{Avg}$).

Averaging

In this mode an arithmetic algorithm will be performed to smoothen the signal. The **Avg. time** is the time constant. This function can be combined

with all other post processing functions. The minimum adjustable average time is 0,1s; on the models 1M, 2M and 3M 1ms (0,001s). On these models values below 0,1s can be increased/ decreased only by values of the power series of 2 (0,002, 0,004, 0,008, 0,016, 0,032, ...).

Peak hold

In this mode the sensor is waiting for descending signals. If the signal descends the algorithm maintains the previous signal peak for the specified **Hold time**.

The minimum adjustable hold time is 1 ms (0,001 s).

After the hold time the signal will drop down to the second highest value or will descend by 1/8 of the difference between the previous peak and the minimum value during the hold time. This value will be held again for the specified time. After this the signal will drop down with slow time constant and will follow the current process temperature. ► **Signal Graphs**

Therefore, if periodic events will be measured (bottles on a conveyor e.g.) this peak hold function avoids a drop down of the signal to the conveyor temperature in-between 2 events.

Valley hold

In this mode the sensor waits for ascending signals. If the signal ascends the algorithm maintains the previous signal valley for the specified **Hold time**. The definition of the algorithm is according to the peak hold algorithm (inverted).

Advanced Peak hold

In this mode the sensor waits for local peak values. Peak values which are lower than their predecessors will only be taken over if the temperature has fallen below the **Threshold** value beforehand. If **Hysteresis** is activated a peak in addition must decrease by the value of the hysteresis before the algorithm takes it as a new peak value.

Advanced Valley hold

This mode is the inverted function of Advanced Peak hold. The sensor waits for local minima. Minimum values which are higher than their predecessors will only be taken over if the temperature has exceeded the **Threshold** value beforehand. If **Hysteresis** is activated a minima in addition must increase by the value of the hysteresis before the algorithm takes it as a new minimum value.

Smart Averaging

If activated, a dynamic average adaptation at high signal edges is active.

Peak picking function


For a detection of fast hotspots (detection time 90 μ s) the averaging time must be set to 0.0 s.

Note




You can display the process temperature T_{Proc} (with post processing) and also the current average temperature T_{Avg} (without any post processing) in the diagram. In this way the result and functionality of the selected post processing features can easily be traced and controlled.

Signal Graphs



— T_{Proc} with Peak Hold (Hold time = 1s)

— T_{Avg} without post processing



— T_{Proc} with Advanced peak hold (Threshold = 80 °C/ Hysteresis = 20 °C)

— T_{Avg} without post processing

3.2. Sensor Setup CT – Output

In the **Output** tab, you can set the **Output 1** and **2** and the **Digital Output AL2**. If the optional **Relay** interface is used, it can also be configured here.


The screenshot shows the configuration interface for the Sensor Setup CT – Output. The interface is divided into three main sections: Output 1, Output 2, and Digital Output AL2. Each section contains various configuration options such as Mode, Source, temperature ranges (TMin, TMax), current ranges (Min, Max), and fail-safe settings. The Output 1 section is configured for Analog mA mode with a TProc source. The Output 2 section is also configured for Analog mA mode with a Tint source. The Digital Output AL2 section is configured for TProc source with a 10.0°C threshold and 0.0°C hysteresis. A Relays section is present but empty.

Section	Mode	Source	TMin [°C]	TMax [°C]	Min [mA]	Max [mA]	FailSafe Min Range [°C]	FailSafe Max Range [°C]	FailSafe min [mA]	FailSafe max [mA]	FailSafe is Active min	FailSafe is Active max
Output 1	Analog mA	TProc	100,0	200,0	4,0	20,0	100,0	200,0	0,0	20,1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Output 2	Analog mA	Tint	0,0	70,0	4,0	20,0	300,0	400,0	0,0	20,1	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Digital Output AL2		TProc	10,0		0,0							

3.2.1. Output 1 and 2


The device has two outputs (OUT-1, OUT-2) which can be configured as desired. The following options are available for selection:

- Off
- Analog mA
- Analog mV
- Alarm mA
- Alarm mV
- TCK



When using the analog mA or mV output, either T_{Proc} , T_{Int} or T_{Box} can be selected as source. The desired temperature measurement range of the sensor can now be set. The range limits can be changed by entering the values in the corresponding fields.

- **TMin:** lower temperature range limit
- **TMax:** upper temperature range limit
- **Min [mA/mV]:** lower limit mA/mV output
- **Max [mA/mV]:** upper limit mA/mV output



Alternatively, outputs 1 and 2 can be used as alarm outputs. To do this, select the **Alarm mA** or **Alarm mV** setting.

As source you can choose between **T_{Proc}**, **T_{Int}** or **T_{Box}**.

Under **Threshold** the threshold value for triggering the alarm is defined.

Hysteresis: Setting the minimum hysteresis

Alarm Off [mA/mV]: Value if no alarm

Alarm On [mA/mV]: Value if alarm

Selecting **Open/Closed** under **Mode** defines the output as High or Low alarm.

Difference mode: When activated, no absolute value is used for the alarm threshold, but the difference between process temperature and ambient temperature (T_{Proc}-T_{Amb}).

Output 1

Mode: Alarm mA ▾

Alarm

Source	TProc ▾
Threshold [°C]	510,0 ▾
Hysteresis [°C]	10,0 ▾
Alarm Off [mA]	0,0 ▾
Alarm On [mA]	0,0 ▾
Mode	Open ▾
Difference Mode	Inactive ▾

3.2.2. Failsafe

The pyrometer has a failsafe function that can be used in analog mode. As source T_{Proc} , T_{Int} or T_{Box} can be selected.

The range can be configured as desired. The settings for fail-safe operation allow the output of a defined level at the analog output depending on defined temperature limits.

Thus a possible cable defect can be detected quickly.

Output 1

Mode: Analog mA

Analog

Source	TProc
TMin [°C]	100,0
TMax [°C]	200,0
Min [mA]	4,0
Max [mA]	20,0
FailSafe Min Range [°C]	100,0
FailSafe Max Range [°C]	200,0
FailSafe min [mA]	0,0
FailSafe max [mA]	20,1

FailSafe is Active min

FailSafe is Active max

3.2.3. Digital Output AL2

The electronic box has an AL2 pin that can be configured as an open-collector output (24 V/ 50 mA) under **Digital Output AL2**.

As source T_{Proc} , T_{Int} or T_{Box} can be selected.

Under **Threshold** the threshold value for triggering the alarm is defined.

Digital Output AL2	
Source:	TProc
Threshold [°C]	10,0
Hysteresis [°C]	0,0
Mode:	Open
Difference Mode:	Inactive

Hysteresis: Setting the minimum hysteresis

Selecting **Open/Closed** under **Mode** defines the output as High or Low alarm.

Difference mode: When activated, no absolute value is used for the alarm threshold, but the difference between process temperature and ambient temperature ($T_{Proc}-T_{Amb}$).

3.2.4. Relays

When using the optional relay interface, T_{Proc} , T_{Int} or T_{Box} can be selected as source.

Under **Threshold** the threshold value for triggering the alarm is defined.

Selecting **Open/Closed** under **Mode** defines the output as High or Low alarm.

Difference mode: When activated, no absolute value is used for the alarm threshold, but the difference between process temperature and ambient temperature ($T_{Proc}-T_{Amb}$).

Relays	
Relay 1	
Source:	TProc
Threshold [°C]	100
Hysteresis [°C]	5,0
Mode:	Open
Difference Mode:	Inactive
Relay 2	
Source:	TInt
Threshold [°C]	70
Hysteresis [°C]	0,0
Difference Mode:	Inactive
Mode:	Open

3.3. I/O Pins

The CT 4M has three I/O pins, which can be programmed as output or input using the software. The following functions are possible:

<u>Function</u>	<u>I/O Pin is on</u>	<u>Description</u>
Alarm	Output (digital)	Open collector output/ definition as High- or Low alarm via normally open/ normally close options in software dialog.
Valid Low	Input (digital)	The output follows the object temperature as long as there is a Low level at the I/O pin. After discontinuation of the Low level the last value will be held.
Valid High	Input (digital)	The output follows the object temperature as long as there is a High level at the I/O pin. After discontinuation of the High level the last value will be held.
Hold Low-High	Input (digital)	The last value will be held if there is a signal with a rising edge on the I/O pin.
Hold High-Low	Input (digital)	The last value will be held if there is a signal with a falling edge on the I/O pin.
Hold Reset Low	Input (digital)	Reset of Peak or valley hold (High-Low signal)
Hold Reset High	Input (digital)	Reset of Peak or valley hold (Low-High signal)
External Emissivity	Input (analog)	The emissivity value can be adjusted via a 0-10 V signal on the I/O pin (scaling possible via software).
Uncommitted value	Input (analog)	Display of uncommitted value
Laser on Low	Input (digital)	Turning on the laser (Low signal)
Laser off High	Input (digital)	Turning on the laser (High signal)
External Ambient compensation	Input (analog)	The ambient temperature will be determined by a voltage on the I/O-pin [0–10 V; range scalable].
External Transmitted compensation	Input (analog)	The transmitted ambient temperature will be determined by a voltage on the I/O-pin [0–10 V; range scalable].

Low/High level: Via Software

When selecting the Alarm function, the following signal sources can be selected:

- **TProc** Process temperature
- **TInt** Temperature of detector
- **TBox** General internal temperature inside the housing

Under **Threshold** the threshold value for triggering the alarm is defined.

Hysteresis: Setting the minimum hysteresis

Selecting **Open/Closed** under **Mode** defines the output as High or Low alarm.

Difference mode: When activated, no absolute value is used for the alarm threshold, but the difference between process temperature and ambient temperature (TProc-TAmb).

The screenshot shows the configuration for I/O Pin 1. The 'Mode' is set to 'Alarm'. Under the 'Parameter' section, the 'Source' is 'TProc', the 'Threshold [°C]' is '510,0', the 'Hysteresis [°C]' is '10,0', the 'Normally' setting is 'Open', and the 'Difference Mode' is 'Inactive'. Below this configuration area, the word 'OUTPUT' is displayed in a large, bold font.

If the function **External Emissivity** is selected, the I/O pin is programmed as analog input. The input can be scaled in the fields **P1 [V]**, **P2 [V]**, **Epsilon P1** and **Epsilon P2**.

When the **Hold Reset Low** or **Hold Reset High** function is selected, the I/O pin is programmed as digital input. When a Low or High level is applied, an activated Hold function (MAX, MIN, extended MAX, extended MIN) is reset.

The image shows two screenshots of a configuration interface. The top screenshot is for I/O Pin 2, where the Mode is set to 'External Emissivity'. Below this, a 'Parameter' section contains four fields: P1 [V] (0.0), P2 [V] (10.0), Epsilon P1 (0.0), and Epsilon P2 (1.1). Below the parameters, the I/O pin is labeled as 'INPUT'. The bottom screenshot is for I/O Pin 3, where the Mode is set to 'Hold Reset High'. Below this, a 'Parameter' section contains two fields: Threshold [V] (0.0) and Hysteresis [V] (0.0). Below the parameters, the I/O pin is labeled as 'INPUT'.

Field	Value
Mode	External Emissivity
P1 [V]	0.0
P2 [V]	10.0
Epsilon P1	0.0
Epsilon P2	1.1

Field	Value
Mode	Hold Reset High
Threshold [V]	0.0
Hysteresis [V]	0.0

3.4. Display

In this tab you can make settings for the display and the backlight (= visual alarms). Furthermore, the temperature unit can be selected here.

3.4.1. Visual Alarms

Independent of the selected signal for the analog output, a signal from the following list can be selected under **General/ Main display Source**, which is shown in the digital display of the electronics:

TProc	Process temperature
TInt	Temperature of detector
TBox	General internal temperature inside the housing

For the visual alarm areas up to eight alarm limits can be assigned to a signal. The selected signal can be selected under **Source** independent of the value shown in the display and independent of the analog output.

Signal Processing | Output | I/O Pins | Display | **Advanced Settings**

General

Main Display Source: TProc

Temperature Unit: Celsius

Visual alarm ranges

Source: TProc

From	To			
0,0 [°C]	5,0 [°C]	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10,0 [°C]	15,0 [°C]	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20,0 [°C]	25,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
30,0 [°C]	35,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
40,0 [°C]	45,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
50,0 [°C]	55,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
60,0 [°C]	65,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
70,0 [°C]	75,0 [°C]	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3.4.2. Temperature unit

Selection between °C and °F as temperature unit.


Temperature Unit:

- Celsius
- Fahrenheit
- Celsius

3.5. Sensor Setup CT – Advanced Settings

The following parameters can be set in the Advanced Settings tab:

- Calibration
- USB Communication
- RS485 Multidrop address
- Locking and unlocking of the programming keys




The screenshot shows the 'Advanced Settings' tab selected in a software interface. The tab is highlighted with a red box. The interface is divided into several sections:

- Calibration:** Contains three settings: 'Mode' set to 'Manual', 'Offset [K]' set to '0,0', and 'Gain' set to '1,00000'.
- USB Communication:** Contains 'Baudrate' set to '115200' and a checked 'Check Sum' option.
- RS485:** Contains 'Multidrop Address' set to '1'.
- User Interface:** Contains an 'Unlocked' button with a key icon.

3.5.1. Sensor Setup CT – Calibration

In the **Advanced Settings** tab, three different modes can be selected to perform a calibration of the device:

- Manual
- 1 Point (Calibration)
- 2 Point (Calibration)




3.5.2. Manual Calibration

For certain applications or under certain circumstances a temperature offset or a change of the gain for the temperature curve may be useful.

The **factory default settings** for Offset and Gain are:

- Offset: 0,0 K
- Gain: 1,000

A changed **Offset** causes a parallel shifting of the temperature curve and therewith it has a linear effect on the temperature reading (change constant independent on process temperature). A change of the **Gain** will have a non-linear effect on the temperature reading (change depends on process temperature).



Calibration

Mode	Manual
Offset [K]	0,0
Gain	1,00000

3.5.3. 1 Point Calibration


In this mode, a 1-point calibration can be made for the device. To do this, select under Mode **1 Point** (Calibration) and enter the **Actual Temperature** and the **Set Temperature**. An offset calculation takes place and is displayed.

Calibration

Mode

Offset [K]

Gain



Calibration

Mode

Offset [K]

Gain

P1


Set Temperature [°C]

Actual Temperature [°C]

3.5.4. 2 Point Calibration

In this mode, a 2 point calibration can be made. To do this, select under Mode **2 Point** (Calibration) and enter the **Actual Temperature** and the **Set Temperature** for two different points. An offset and gain is then calculated.

Calibration	
Mode	2 Point
Offset [K]	0,0
Gain	1,00000



Calibration	
Mode	2 Point
Offset [K]	-1,2
Gain	0,99269

P1	
Set Temperature [°C]	19,5
Actual Temperature [°C]	18,2

P2	
Set Temperature [°C]	389,0
Actual Temperature [°C]	385,0

3.5.5. USB Communication

Under USB communication the baud rate of the sensor can be selected. You can choose between 115200 and 921600. With activation of the check sum

USB Communication

Baudrate:

Check Sum

3.5.6. RS485-Multidrop address


In combination with a RS485 interface you can build a network of several CT sensors (max. 32 sensors). For the digital communication each sensor must have its own address which you can enter in the input field Multidrop address. [▶ RS485/ RS422](#)

RS485

Multidrop Address:

3.5.7. Locking the programming keys


With this function you can lock the programming keys on the CT electronics to avoid a non-authorized change of parameters on the unit. Pressing the button will set the unit into the **Locked** or **Unlocked** mode. In the locked mode all parameter and settings can be displayed on the unit by pressing the **Mode** button – a change of parameters with the **Up** or **Down** button is not possible.



4. Special Feature

4.1. Saving the Sensor Configuration

In each window which you enter with the button **Setup** [Menu: **Device\ Device Setup**] you will find at the bottom edge the following buttons for saving of the sensor configuration:



Save Config

With this button you can save the current configuration of the connected sensor in a file (ending: *.cfg). An explorer window will be opened and enables definition of filename and destination.

Load Config

A previous saved configuration can be opened and stored into the connected sensor.

Factory default


This button enables the user to reset the unit to the factory default values. It also can be reset by pressing at first the **Down** button and then the **Mode** button (keep both pressed for approx. 3 seconds).

After pressing **OK** all changes and settings will apply.


4.2. Smart Averaging

The average function is generally used to smoothen the output signal. With the adjustable parameter time this function can be optimal adjusted to the respective application. One disadvantage of the average function is that fast temperature peaks which are caused by dynamic events are subjected to the same averaging time. Therefore those peaks can only be seen with a delay on the signal output.

The function **Smart Averaging** eliminates this disadvantage by passing those fast events without averaging directly through to the signal output.




Signal graph with Smart Averaging function



Signal graph without Smart Averaging function

4.3. Binary Chat Program

In the download package you will find an additional program for a simple check of the digital communication of the connected sensor. Please copy the application (BinaryChat.exe) out of the folder **\Binary Chat Program** on your desktop or into any desired folder on your hard disc drive of your PC. After starting the program the following window will appear:



Please select at first the COM port of the connected sensor (you will find this information in the status line of your CompactPlus Connect or in the device manager of your PC).

Please enter the **Baudrate** your sensor is working with.

Now you can open the COM port by pressing the button **Open COM**.




Note

Before you open the COM port please close the CompactPlus Connect software as this application may access the same sensor/ COM port.

Please make sure that the sensor is set to **bidirectional digital communication**.

Now you can enter a binary command as hexadecimal value out of the according command list of the connected sensor. After pressing **Send** the answer will be shown in the line **Receive** (also as HEX value). Below the receive line you will find the **Integer** decimal value of the answer as well as the calculated **Temperature** or the **Decimal** value which is calculated by dividing the answer by 1000. This calculation is used for the emissivity value e.g.



Example 1: CTratio/ Polling of the process temperature

Example 1 shows the polling of the process temperature from a CTratio. This is done according to the command list (Folder: Commands):

1 Basic Functions						
DECIMAL	HEX	Command	Data	Answer	Result	Unit
1	0x01	READ Temp. - Process	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
2	0x02	READ Temp. - Det	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
3	0x03	READ Temp. - Box	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
10	0x0A	READ Temp. - Ratio	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
11	0x0B	READ Temp. - T2	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
12	0x0C	READ Temp. - T1	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	°C
13	0x0D	READ Temp. - Attenuation	none	byte1 byte2	$= (\text{byte1} * 256 + \text{byte2} - 1000) / 10$	%

4.3.1. Additional Features

Under **Averaging** you can calculate the average value out of a defined number of values **Count**.

If you press the button **Start Timer** you can activate a repeated polling of values (useful for process temperature e.g.). The polling **Interval** can be set (in ms).

Please use only times >50 ms, as otherwise you may receive wrong data.

5. Menu Overview

Using the menu you can adjust all software settings. Each feature will be explained in detail in the following chapters of this manual:



5.1. Menu: File

Save Diagram


To save temperature files

Open Diagram

To open saved temperature files (*.dat)

Exit

To exit the program



5.2. Menu: Measurement

Start

To start the measurement

Pause

To freeze the continuous diagram actualization

Stop


To stop the measurement

Settings

Opens the window: **Measurement Settings**

Configure Burst String

In the burst mode the sensor works in a unidirectional communication mode – the sensor is sending data continuously.



5.3. Menu: Device

Scan Devices

Scans for connected sensors (if Auto scan is deactivated)

Disconnect

The connection will be determined and the COM port will be closed.

Device Info

Shows information about the connected unit (firmware revision etc.).

Device Setup...


Opens the window: Device setup

Loop Maintenance

Verification of the analog output channels

Laser



To switch On and Off the Laser




5.4. Menu: Diagram

Settings

Opens the window: **Diagram settings** to select digital displays, temperature graphs, pen width and color of graphs



CT 4M



CTratio

5.5. Menu: View

Title bar	To show or hide the title bar of the software window
Menu bar	To show or hide the menu bar of the software window
Tool bar	To show or hide the tool bar
Tool bar captions	To show or hide the captions of the tool bar
Status bar	To show or hide the status bar

Digital Selection of all available values which can be shown as a digital display






Diagram	To show or hide the temperature diagram
Always on top	If activated, the software screen will always visible on top (independent on other active applications)
Enable Video	To switch on and off the video display
Video snapshot	To make a snapshot
Temp. displays top	The digital display group will be located on the top right corner of the software screen
Temp. display right	The digital display group will be located on the right side of the software window
Show all bars	All bars will be shown (title-, menu-, tool- and status-bar)
Hide all bars	All bars will be hidden (title-, menu-, tool- and status-bar)
External Display	To open an external display
Log window	Display of logged software events



5.6. Menu: Preferences

Options


Opens the window: **Options** to make basic settings and define options for data saving

Language

To select the desired language

Set default software settings

The software will be reset to the factory default settings (The sensor settings are not affected by this)



5.7. Menu: Help

Help...


To open the help file

www.optris.global

Opens the Optris homepage in your web browser


About...

To show the software version installed on your computer




5.8. Context Menu (right mouse button)

- Settings** Opens the window: **Diagram settings** to select digital displays, temperature graphs, pen width and color of graphs
- View** Linking to the sub menu **View**



5.9. Context Menu [Sub menu: View]

Title bar	Shows or hides the title bar
Menu bar	Shows or hides the menu bar
Tool bar	Shows or hides the tool bar
Tool bar captions	Shows or hides the tool bar captions
Status bar	Shows or hides the status bar
Diagram	Shows or hides the diagram
Temperature Display top	Places the digital displays on top of the diagram
Temperature Display right	Places the digital displays right of the diagram
Show all bars	Shows all bars at once
Hide all bars	Hides all bars at once
External display	Linking to the sub menu External display
Log window	Display of logged software events



5.10. Context-Menu [Sub menu: External Display]

In this menu you can call separate digital displays for the different signals. These displays will also be shown if the application runs in the invisible mode. The displays are always on top of the PC screen.

